

#### The State of New Hampshire

### Department of Environmental Services



Michael P. Nolin Commissioner

Salem School District SAU 57 38 Geremonty Drive Salem, NH 03079

Re: Lancaster School, 54 Millville Street Salem, UST # 0-112825

North Salem Elementary School, 140 Zion Hill Road, Salem, UST #0-112826

Barron School, 14 Butler Street Salem, UST #0-112828

Mary Fisk School, 14 Main Street Salem, UST #0-112829

Walter Haigh School, 24 School Street Salem, UST #0-112830

Salem High School, 44 Geremonty Drive Salem, UST # 0-112832

Woodbury School, 206 Main Street Salem, UST #0-112831

NOTICE OF PROPOSED ADMINISTRATIVE FINE AND LICENSE ACTION NO. AF 05 - 050

June 23, 2005

#### I. Introduction

This Notice of Proposed Administrative Fine and License Action is issued by the Department of Environmental Services, Waste Management Division to Salem School District SAU 57. Pursuant to RSA 146-C:10-a and NH Admin. Rule Env-C 600, the Division is proposing that fines totaling \$10,100 be imposed against the Salem School District SAU 57 for the violations alleged below. Also, pursuant to RSA 541-A:30, RSA 146-C:4, and Env-Wm 1401.09, the Division is proposing that DES suspend the permits to operate the underground storage facilities held by Salem School District SAU 57, based on the violations alleged below. This notice contains important procedural information. Please read the entire notice carefully.

#### II. PARTIES

1. The Department of Environmental Services, Waste Management Division ("the Division"), is a duly constituted administrative agency of the State of New Hampshire, having its principal office at 29 Hazen Drive, Concord, NH 03301.

2. Salem School District SAU 57 ("SAU 57") is a duly-constituted School Administrative Unit of the State of New Hampshire having a mailing address of 38 Geremonty Drive, Salem, NH 03079.

#### III. SUMMARY OF FACTS AND LAW SUPPORTING CLAIMS

- 1. RSA 146-C authorizes the Department of Environmental Services ("DES") to regulate the installation, maintenance, operation, licensing and closure of underground storage facilities. Pursuant to RSA 146-C:9, the Commissioner of DES has adopted N.H. Admin. Rules Env-Wm 1401 to set forth the requirements for underground storage facilities by "establishing criteria for registration and permitting, and standards for design, installation, operation, maintenance, and monitoring of such facilities."
- 2. RSA 146-C:10-a authorizes the Commissioner to impose administrative fines of up to \$2,000 per offense upon any person who violates any provision of RSA 146-C or any rule adopted under the provisions of this chapter. Pursuant to RSA 146-C:10-a, the Commissioner has adopted Env-C 607 to establish the schedule of fines for such violations.
- 3. RSA 146-C:4 prohibits the operation of an underground storage facility in New Hampshire without a permit. The permit to operate is issued by, and may be revoked by DES in accordance with RSA 541-A:30 for just cause, including, but not limited to, the operation or ownership of an underground storage facility in violation of DES's rules. Pursuant to RSA 146-C:9, the Commissioner has adopted Env-Wm 1401 regarding the ownership, registration and operation of underground storage tanks and facilities including criteria for issuing, renewing and revoking a permit to operate an underground storage tank or facility in New Hampshire.
- 4. SAU 57 is the registered facility owner of one underground storage tank ("UST") at the Lancaster School facility, further identified as UST #0112825, located on real property at 54 Millville Street, Salem, NH. DES previously issued permit to operate No. 0112825 to SAU 57, to allow the operation of the UST at the Lancaster School facility.
- 5. The Lancaster School facility UST system is subject to the requirements of RSA 146-C and Env-Wm 1401.
- 6. On May 20, 2004, a Division inspector conducted a compliance inspection at the Lancaster School facility and noted compliance deficiencies which were identified in a report issued to the Lancaster School facility representative at the time of the inspection.
- 7. The report notified the Lancaster School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Lancaster School facility.
- 8. The Lancaster School report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. The permit was not posted at the Lancaster School facility; and

- b. The piping for the 10,000-gallon #2 fuel oil UST (Lancaster School facility Tank 2) is not corrosion protected.
- 9. SAU 57 is the registered facility owner of one UST at the North Salem Elementary School facility, further identified as UST # 0112826, located on real property at 140 Zion Hill Road, Salem, NH. DES previously issued permit to operate No. 0112826 to SAU 57, to allow the operation of the UST at the North Salem Elementary School facility.
- 10. The North Salem Elementary School facility UST system is subject to the requirements of RSA 146-C and Env-Wm 1401.
- 11. On May 20, 2004, a Division inspector conducted a compliance inspection at the North Salem Elementary School facility and noted compliance deficiencies which were identified in a report issued to the North Salem Elementary School facility representative at the time of the inspection.
- 12. The report notified the North Salem Elementary School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the North Salem Elementary School facility.
- 13. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. The permit was not posted at the North Salem Elementary School facility;
  - b. The overfill protection device for the 10,000-gallon #2 fuel oil UST (North Salem Elementary School facility Tank 2) was not properly installed; and
  - c. The piping for North Salem Elementary School facility Tank 2 is not corrosion protected.
- 14. SAU 57 is the registered facility owner of one UST at the Barron School facility, further identified as UST #0112828, located on real property at 14 Butler Street, Salem, NH. DES previously issued permit to operate No. 0112828 to SAU 57, to allow the operation of the UST at the Barron School facility.
- 15. The Barron School facility UST system is subject to the requirements of RSA 146-C and Env-Wm 1401.
- 16. On May 20, 2004, a Division inspector conducted a compliance inspection at the Barron School facility and noted compliance deficiencies which were identified in a report issued to the Barron School facility representative at the time of the inspection.
- 17. The report notified the Barron School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Barron School facility.

- 18. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. The permit was not posted at the Barron School facility; and
  - b. The piping for the 10,000-gallon #2 fuel oil UST (Barron School facility Tank 2) is not corrosion protected.
- 19. SAU 57 is the registered facility owner of one UST at the Mary Fisk School facility, further identified as UST #0112829, located on real property at 14 Main Street, Salem, NH. DES previously issued permit to operate No. 0112829 to SAU 57, to allow the operation of the UST at the Mary Fisk School facility.
- 20. The Mary Fisk School facility UST system is subject to the requirements of RSA 146-C and Env-Wm 1401.
- 21. On May 20, 2004, a Division inspector conducted a compliance inspection at the Mary Fisk School facility and noted compliance deficiencies which were identified in a report issued to the Mary Fisk School facility representative at the time of the inspection.
- 22. The report notified the Mary Fisk School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Mary Fisk School facility.
- 23. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. The permit was not posted at the Mary Fisk School facility; and
  - b. The piping for the 8,000-gallon #2 fuel oil UST (Mary Fisk School facility Tank 2) is not corrosion protected.
- 24. SAU 57 is the registered facility owner of one UST at the Walter Haigh School facility, further identified as UST #0112830, located on real property at 24 School Street, Salem, NH. DES previously issued permit to operate No. 0112830 to SAU 57, to allow the operation of the UST at the Walter Haigh School facility.
- 25. The Walter Haigh School facility UST system is subject to the requirements of RSA 146-C and Env-Wm 1401.
- 26. On May 20, 2004, a Division inspector conducted a compliance inspection at the Walter Haigh School facility and noted compliance deficiencies which were identified in a facility report issued to the Walter Haigh School facility representative at the time of the inspection.

- 27. The report notified the Walter Haigh School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Walter Haigh School facility.
- 28. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. The permit was not posted at the Walter Haigh School facility; and
  - b. The piping for the 6,000-gallon #2 fuel oil UST (Walter Haigh School facility Tank 2) is not corrosion protected.
- 29. SAU 57 is the registered facility owner of two UST systems at the Woodbury School facility, further identified as UST #0112831, located on real property at 206 Main Street, Salem, NH. DES previously issued permit to operate No. 0112831 to SAU 57, to allow the operation of the UST systems at the Woodbury School facility.
- 30. The Woodbury School facility UST systems are subject to the requirements of RSA 146-C and Env-Wm 1401.
- 31. On May 20, 2004, a Division inspector conducted a compliance inspection at the Woodbury School facility and noted compliance deficiencies which were identified in a facility report issued to the Woodbury School facility representative at the time of the inspection.
- 32. The report notified the Woodbury School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Woodbury School facility.
- 33. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. A current registration form for the Woodbury School facility is not on file with DES;
  - b. The permit was not posted at the Woodbury School facility; and
  - c. The piping for the 10,000-gallon #2 fuel oil UST (Woodbury School facility Tank 2) is not corrosion protected.
- 34. SAU 57 is the registered facility owner of two UST systems at the Salem High School facility, further identified as UST #0112832, located on real property at 44 Geremonty Drive, Salem, NH. DES previously issued permit to operate No. 0112832 to SAU 57, to allow the operation of the UST systems at the Salem High School facility.
- 35. The Salem High School facility UST systems are subject to the requirements of RSA 146-C and Env-Wm 1401.

- 36. On May 20, 2004, a Division inspector conducted a compliance inspection at the Salem High School facility and noted compliance deficiencies which were identified in a facility report issued to the Salem High School facility representative at the time of the inspection.
- 37. The report notified the Salem High School facility that compliance was to be achieved within 30 days of the date of the inspection and verification of compliance submitted to the Division within 45 days of the date of the inspection. Acknowledgement of receipt of the report was signed by John C. Watkevitch on behalf of the Salem High School facility.
- 38. The report also included a UST Facility Summary of Deficiencies identified at the time of the inspection. Among those deficiencies identified, the Division was not notified that the following were corrected within 45 days after the inspection was performed:
  - a. A current registration form for the Salem High School facility is not on file with DES;
  - b. The permit was not posted at the Salem High School facility;
  - c. The spill containment device for the 10,000-gallon #2 fuel oil UST (Salem High School facility Tank 3) was not able to provide the minimum 5-gallon capacity; and
  - d. The piping for the 15,000-gallon #2 fuel oil UST (Salem High School facility Tank 4) is not corrosion protected.
- 39. Env-Wm 1401.04(a) requires the owner of an underground storage facility to register the facility by providing the information required by RSA 146-C:3, I and II.
- 40. Env-Wm 1401.07(c) requires a permit to be displayed so it is visible and permanently affixed on the facility premises.
- 41. Env-Wm 1401.25(c) requires all spill containment equipment to have a minimum liquid capacity of 5-gallons.
- 42. Env-Wm 1401.25(d) defines the manner in which the overfill protection devices shall be installed.
- 43. Env-Wm 1401.33(b) requires corrosion protection be installed on regulated piping prior to December 22, 1998.

# IV. VIOLATIONS ALLEGED, PROPOSED LICENSE ACTION, AND ADMINISTRATIVE FINE(S)

- 1. SAU 57 has violated Env-Wm 1401.04(a) by failing to provide DES with a current registration form for the Woodbury School and Salem High School facilities. For this violation, Env-C 607.02(a) specifies a fine of \$1,000 per requirement not met, or \$2,000 for the two facilities.
- 2. SAU 57 has violated Env-Wm 1401.07(c) by failing to display and permanently affix permits at the Lancaster School, North Salem Elementary School, Barron School, Mary Fisk School, Walter Haigh School, Woodbury School, and Salem High School facilities. Env-C 607.02(b) specifies a fine of \$100 per permit not posted, or \$700 for the seven facilities.

- 3. SAU 57 has violated Env-Wm 1401.25 (c) and (d) by failing to maintain a minimum liquid capacity of 5-gallons in the spill containment equipment for the Salem High School facility Tank 3 and properly install and maintain overfill protection equipment on the North Salem Elementary School facility Tank 2. For this violation, Env-C 607.05(j) specifies a fine of \$200 per requirement not met or \$400 for the two facilities.
- 4. SAU 57 has violated Env-Wm 1401.33(b) by failing to install corrosion protection for the piping systems of the Lancaster School facility Tank 2, the North Salem Elementary School facility Tank 2, the Barron School facility Tank 2, the Mary Fisk School facility Tank 2, the Walter Haigh School facility Tank 2, the Woodbury School facility Tank 2, and the Salem High School facility Tank 4. For this violation Env-C 607.03(f) specifies a fine of \$1,000 per requirement not met or \$7,000 for the seven facilities.
- 5. Based on the violations identified above, the Division proposes that DES revoke the permits to operate the UST systems at all seven facilities.

The total fine being sought is \$10,100.

#### V. REQUIRED RESPONSE, OPPORTUNITY FOR HEARING

Pursuant to Env-C 601.06, SAU 57 is required to respond to this notice. Please respond no later than July 28, 2005 using the enclosed colored form.

SAU 57 has the right to a hearing to contest these allegations before the proposed license action is taken or any administrative fine is imposed. The hearing would be a formal adjudicative proceeding pursuant to RSA 541-A:31, at which SAU 57 and any witnesses SAU 57 may call would have the opportunity to present testimony and evidence as to why the proposed action should not be taken. All testimony at the hearing would be under oath and would be subject to cross examination. If SAU 57 wishes to have a hearing, one will be scheduled promptly.

RSA 541-A:31, III(e) provides that SAU 57 has the right to have an attorney present to represent SAU 57 at SAU 57's expense. SAU 57 is not required to be represented by an attorney. If SAU 57 chooses to be represented by an attorney, the attorney must file an appearance and comply with NH Admin. Rule Env-C 200.

- 1. If SAU 57 would like to have a hearing, please have an authorized representative sign the appearance section of the colored form (upper portion), check the appropriate line requesting a **formal hearing** and return it to the DES Legal Unit, at the address noted on the form.
- 2. If SAU 57 wishes to discuss the possibility of settling the case, please have an authorized representative sign the appearance form, check the appropriate line indicating a desire to **meet informally** and return it to the DES Legal Unit.
- 3. If SAU 57 chooses to waive the hearing, relinquish the permit to operate and/or pay the proposed fine, please have an authorized representative sign the waiver (lower portion) and return it with payment of the fine to the DES Legal Unit.

#### VI. DETERMINATION OF LIABILITY FOR ADMINISTRATIVE FINES

Pursuant to Env-C 601.09, in order for any fine to be imposed after a hearing, the Division must prove, by a preponderance of the evidence, that SAU 57 committed the violations alleged and that the total amount of fines sought is the appropriate amount under the applicable statute and rules. Proving something by a preponderance of the evidence means that it is **more likely than not** that the thing sought to be proved is true.

If the Division proves that SAU 57 committed the violations and that the total amount of fines sought is the appropriate amount under the applicable statute and rules, then the fine sought will be imposed, subject to the following:

- \* Pursuant to Env-C 601.09(c), the fine will be reduced by 10% for each of the circumstances listed below that SAU 57 proves, by a preponderance of the evidence, applies in this case:
  - 1. The violation was a one-time or non-continuing violation, and SAU 57 did not know about the requirement when the violation occurred, and the violation has not continued or reoccurred as of the time of the hearing, and any environmental harm or threat of harm has been corrected, and SAU 57 did not benefit financially, whether directly or indirectly, from the violation.
  - 2. At the time the violation was committed, SAU 57 was making a good faith effort to comply with the requirement that was violated.
  - 3. SAU 57 has no history of non-compliance with the statutes or rules implemented by DES or with any permit issued by DES or contract entered into with DES.
  - 4. Other information exists which is favorable to SAU 57's case which was not known to the Division at the time the fine was proposed.

# \*\*\*\*\*<u>IMPORTANT</u> <u>NOTICE</u>\*\*\*\*\*

An administrative hearing is a formal hearing. All hearings will be recorded, and all witnesses will testify under oath or affirmation. At the hearing, the Division will present testimony and evidence to try to prove that SAU 57 committed the violation(s) alleged above, that the proposed license action be taken and proposed fine(s) be imposed. The hearing is SAU 57's opportunity to present testimony and evidence that SAU 57 did not commit the violation(s), that the proposed license action should not be taken and/or that the fine(s) should not be imposed, or that the fine(s) sought should be reduced. If SAU 57 has any evidence, such as photographs, business records or other documents, that SAU 57 believes show that SAU 57 did not commit the violation(s) or that otherwise support SAU 57's position, then SAU 57 should bring the evidence to the hearing. SAU 57 may also bring witnesses (other people) to the hearing to testify on SAU 57's behalf.

\*\*\*\*\*

Information regarding this proposed license action and fine may be made available to the public via the DES Web page (www.des.nh.gov). If SAU 57 has any questions about this matter, please contact the DES Legal Unit, at (603) 271-7509.

Anthony P. Giunta, P.G.

Director

**DES Waste Management Division** 

Enclosure (NHDES Fact Sheet #CO-2002)

cc: Michael J. Walls, DES Assistant Commissioner
Jennifer J. Patterson, Sr. Asst. Attorney General, NHDOJ/EPB
James Martin, DES Public Information Officer
Kerry D. Barnsley, Compliance Attorney, DES Legal Unit
Lynn A. Woodard, P.E., WMD UST Supervisor
Thomas R. Beaulieu, WMD UST Chief
Tammy Calligandes, WMD

## \*\*\* RETURN THIS PAGE ONLY \*\*\*

# SALEM SCHOOL DISTRICT SAU 57 IS REQUIRED BY LAW TO RESPOND TO THIS NOTICE.

## PLEASE RESPOND NO LATER THAN July 28, 2005

Please check the appropriate line and table APPEARANCE On behalf of SAU 57:	fill in the requested information below.
I request to have a formal he	aring scheduled in this matter.
I would like to meet informa	ally to discuss the issues in this matter.
WAIVER OF HEARING On behalf of SA	AU 57:
license action and that I hereby waive	right to a hearing regarding the imposition of the proposed those rights and relinquish UST permits to operate Nos. 2829, 0112930, 0112831 and 0112832.
	right to a hearing regarding the imposition of the proposed y waive those rights. The fine payment in the amount of lew Hampshire" is enclosed.*
funds, pursuant to NH RSA 6:11-a, DI amount of the original check draft, or	aft, or money order that is returned due to insufficient ES may charge a fee in the amount of 5% of the face money order or \$25.00, whichever is greater, plus all ollecting the amount of the original check draft, or money
Pursuant to Env-C 203.05 please pro	ovide the following information:
Signature	Date
Name (please print or type):	
Title:	
Phone:	
RETURN THIS PAGE ONLY AND DES Legal Unit Attn: Michael Sclofoni, Legal Assist	

DES Legal Unit
Attn: Michael Sclafani, Legal Assistant
P.O. Box 95
Concord, NH 03302-0095

# ENVIRONMENTAL

# Fact Sheet



29 Hazen Drive, Concord, New Hampshire 03301 • (603) 271-3503 • www.des.nh.gov

CO-2

2002

# Administrative Fines of the Department of Environmental Services

The Commissioner of the Department of Environmental Services (DES) is authorized by several statutes to impose administrative fines for certain violations of those statutes. In order to implement this authority, the Commissioner has adopted rules which specify the procedures for notifying people that a fine is being proposed and which specify the fine amount for any given violation. These rules are identified as Chapter Env-C 600.

Administrative fine proceedings follow a defined path. The first step is for a Division of DES to issue a Notice of Proposed Fine. The Notice will inform you of the violations the Division believes you have committed, together with the dollar amount of the fine that is being proposed. At this point, a final decision as to whether to impose the fine has not been made ... the Notice simply initiates the proceeding. The Notice will also inform you that you have a right to have a hearing before a final decision will be made, and may give a date and time for the hearing.

The Notice you receive will have a page attached to it on which you can indicate whether you will attend a hearing or whether you are waiving your right to a hearing and paying the fine which has been proposed. YOU MUST COMPLETE AND RETURN THIS FORM. The worst thing you can do if you receive a Notice is to ignore it! Under the rules which have been adopted, the case can proceed even if you don't respond. In order to achieve the best result, you must participate in the process.

When you receive a Notice of Proposed Fine, if you are interested in trying to settle the case without going to a formal hearing you should contact the person identified in the Notice. Many fine cases are settled in this way, often with a lower fine, a payment schedule, and/or a suspended fine. The negotiations need to start soon after the Notice is received, though. Don't wait until the day scheduled for the hearing to ask about settling the case.

If the case proceeds to a hearing, the Commissioner will designate a person to serve as a hearing officer to preside at the formal hearing. The hearing officer will not have prior knowledge of the Division's allegations, and will be neutral insofar as the outcome of the case is concerned. At the hearing, the Division will be required to prove that the violation(s) occurred and that the proposed fine is warranted. You will have an opportunity to ask questions of (cross-examine) the Division staff, and also present your own evidence, including testimony of witnesses if you wish, to show why the fine should not be imposed.

(over)

After the hearing is over, the hearing officer will compile the record (i.e. all of the information that was received at the hearing) and will make a recommendation to the Commissioner as to whether or not the fine should be imposed. The Commissioner will make a decision based on the evidence and testimony, and the decision issued by the Commissioner will specifically state the reasons for the decision.

The rules adopted by the Commissioner require the proposed fine to be reduced in certain circumstances, which are listed at Env-C 601.09. These include that you have not previously violated a law or rule implemented by DES, or that you acted in good faith. The Commissioner also has the discretion to allow you to pay a fine on a payment schedule, and/or to suspend all or a portion of the fine conditional upon remedying the underlying violation or staying in compliance with DES requirements for a specified period of time.

Sometimes people are concerned that the findings and rulings made by the Commissioner might be used against them in a separate proceeding (for instance, if their neighbor sues them for damages arising out of the same violation(s) for which they are being fined). In such a case, DES has accepted payment of the fine with a specific denial of liability. This is like pleading "no contest" to a traffic ticket: you pay the fine assessed, but are not admitting that you did anything wrong.

This fact sheet is intended as a basic source of information concerning DES administrative fines. It is not intended to replace the laws and rules regarding administrative fines, but merely to provide a summary of them.

For more information contact the DES Legal Unit, PO Box 95, Concord, NH 03302-0095, (603) 271-6072.